

BLACK SHIELD CHECK LIST (as of 14 Jul 67)

Page 2

H-Minus	25X1	ACTION	DOI	RESP INDV	TIME DUE(Z)	TIME DUE(L)	TIME DONE(L)	DONE BY (Initials)	
-10:00		(Terminal wx fcsts)	B-5	B Festr	13/1610	14/0110	0110	TY	
-9:00		D-NO GO wx fcsts)	B-11	"	1710	0210	0130	TY	
-9:00		out to Msn Coord	B-23	"	1710	0210	0100	TY	
-8:00		thru L-hr, if reqd)	B-16	B&A FESTRS	1810	0310			
		Annotate tanker DD Forms 175	B-24				0610	<i>MM</i>	
25X1	Brief tankers		B-24		2110	0610	0610	<i>MM</i>	
-4:00	Send	(Terminal wx fcsts)	B-5		2210	0710	0710	<i>MM</i>	
-4:00	Send	(Met Watch obs)	B-18		2210	0710	0710	<i>MM</i>	
	Brief tankers		B-24		2230	0730	0740	<i>MM</i>	
-3:30	Brief pilots and ops staff		B-20		2240	0740	0740	DEB	
25X1	Brief tankers		B-24		2300	0800	0810	<i>MM</i>	
-3:00	Rcv	Amend (GO/NO GO fcsts)	B-11		2310	0810	0722	DEB	
-3:00	Rcv	Letdown Plates from DCO	B-14		2310	0810	0820	DEB	
-3:00	Enter fcsts on Letdown Plates		B-14		2310	0810	0905	DEB	
-2:30	Msn Obsvr to CP; posts data		B-13		2340	0840	0845	RAF	
25X1									
-2:00		(Wx Scout reports)	B-22		14/0010	0910			
25X1	Pick up APT pictures		B-10		0900 or ASAP	0900 or ASAP			
-1:40	Msn Festr to CP; Obsvr to wx str	B-13			0030	0930	1030	DEB	
-1:35	Letdown plate fcsts to pilots (Notify Mission Coordinator)	B-14			0035	0935	1015	DEB	
-1:30	Notify DCOL (If need to rebrief pilots)	B-20			0040	0940	—	—	
-1:10	Rebrief pilots if necessary	B-20			0000	1000	—	—	
L-Plus	<i>PICK UP APT PICTURES (NINER)</i>							<i>Recalled 1140L</i>	
	Landing time: 14/	Z	L						
25X1	+0:15	Return Met Watch to wx station	B-13						
	+0:15	Start debriefing form	B-15						
	+0:45	Attend pilot debriefing	B-15						
ASAP	Give	input to DCOM Coord after debriefing	B-15		ASAP	ASAP			
	+24:00	Turn in Msn Wx File to Intell	B-17						
								25 YEAR RE-REVIEW	

BEST COPY
Available
THROUGHOUT
FOLDER

Page Denied